



**National
Aeronautical
Laboratory**

Documentation Sheet

Document Classification
Restricted

Title : Report on Failed High Pressure
Turbine Rotor Blades

Document No.

PD MT 8922

Date of issue: June 1989

Author(s) : A.C.Raghuram, R.Rangaraju,
R.V.Krishnan and M.A.Venkataswamy

Contents 1 page
2 figures

Division : Materials Science

No. of copies: 10

External participation : -

NAL Project No.
MT- 9 - 001

Sponsor : -

Sponsor's Project No.

Approval : Dr A.C.Raghuram

Remarks : -

Keywords : Turbine blade, impact damage

Abstract : An investigation of damages sustained by the high pressure turbine rotor blades of an aeroengine has been carried out at the request of Hindustan Aeronautics Limited, Koraput.